

# Honeywell Total Connect® 2.0 Compatibility Chart

PRODUCT	SOFTWARE REVISION (OR HIGHER)
<b>VISTA™ CONTROL PANELS – RESIDENTIAL</b>	
VISTA-21iP, VISTA-21iPSIA	Panel EEPROM Revision: 3.13 Internal Communicator SW Revision: 2.6.42
VISTA-20P, VISTA-20PSIA FA168CPS, FA168CPSSIA VISTA-15P, VISTA-15PSIA FA148CP, FA148CPSIA	9.12
<b>VISTA CONTROL PANELS – COMMERCIAL</b>	
VISTA-128BPT V128BPTSIA FA166OCT	All Revisions
<b>LYNX PLUS</b>	
L3000	20.1
<b>LYNX TOUCH</b>	
L5200 L5210 L7000	All Revisions
<b>ALARMNET® COMMUNICATORS</b>	
7847i	2.6.42
GSMV4G iGSMV4G GSMX4G CDMA-X	All Revisions
<b>CONNECTED HOME AND BUSINESS MODULES</b>	
TUXWIFIW TUXWIFIS	4.4.32W
VAM	SW 6.1.10
Lyric™ Lyric AIO Lyric Gateway	All Revisions All Revisions

**For more information**

[www.honeywell.com/security](http://www.honeywell.com/security)

**Honeywell Security and Fire**

2 Corporate Center Dr. Suite 100  
P.O. Box 9040  
Melville, NY 11747  
1.800.323.4576  
[www.honeywell.com](http://www.honeywell.com)

Honeywell reserves the right, without notification, to make changes in product design or specifications.

L/TC20COMPFD | 09/17  
© 2017 Honeywell International Inc.